





DRY METHOD DECAL APPLICATION INSTRUCTIONS

IMPORTANT!! Clean application surface with a synthetic, free rinsing detergent. Avoid soaps containing creams or lotions.

Painted surfaces must be properly cured prior to application of decals. Undercured paint can cause bubbling of the graphics. Decal will NOT adhere to dusty, dirty, or greasy areas. Do not attempt to apply decals when the temperature of the surface is below 50 F.




1. Leaving the backing sheet on, position decal on application surface and tape in place. With tape make a horizontal hinge at the top of the decal.




2. Pull off the backing sheet exposing the adhesive. Leaving the top of the decal hinged to the surface.



3. Pull decal to stretch out flat. Gently press down in corners to hold in place.



4. Rub decal onto surface with a plastic squeegee, working from the center to the edges, smoothing decal out gradually so as to avoid any air bubbles.



5. Slowly pull off pre-mask strip. If any air bubbles appear, puncture them with a pin and squeegee the air out.

Not responsible for misapplied decals.